


OFFICE OF THE ASSISTANT ENGINEER P.W.D.,PALI

SAFETY CERTIFICATE

This is to certified that I have physically inspected Emmanuel Mission Senior Secondary school building, Pali on 20/1/2017 along with my subordinate and found the building structurally safe under normal conditions for the year 2017-18.

Date:- 20.01.2017


सहायक अभियंता 20/1/17
Assistant Engineer
सा.वि.नि. पावसा 2, पाली
P.W.D., Pali